

ABSTRAK

ANALISA KESEHATAN DAN KESELAMATAN KERJA (K3) PADA PROJECT PERTAMINA GEOTHERMAL ENERGY DESA PENINDAIAN KEC. SEMENDO DARAT LAUT PROVINSI SUMATERA SELATAN

M. Ridho Erlandi
Ir. Yuliantini Eka Putri,S.T,M.T
Ir. Marinda Gusti Akhiria,S.T,M.T

Kinerja merupakan tingkat keberhasilan seseorang secara keseluruhan dalam periode tertentu didalam melaksanakan tugas dibanding dengan berbagai kemungkinan seperti standar hasil kerja target sasaran atay kinerja yang telah ditentukan terlebih dahulu dan telah disepakati bersama. Hal ini dapat tercapai apabila perusahaan selalu memperhatikan faktor keselamatan dan kesehatan kerja (K3) karena itu akan dapat meningkatkan kinerja karyawan. Masalah yang sering muncul dalam perusahaan saat ini adalah kurangnya perhatian terhadap aspek manusiawi. Berdasarkan hasil penelitian dan analisis mengenai kesehatan dan keselamatan kerja (K3) pada proyek PT Pertamina Geothermal Energy (PGE) Kecamatan Semendo Darat Laut disimpulkan menjadi beberapa hal. Kondisi implementasi K3 telah dilakukan namun beberapa kekurangan yang mempengaruhi efektifitasnya. Faktor resiko utama berasal dari minimnya pencahayaan di area kerja dan kurangnya pengawasan terhadap pelaksanaan prosedur keselamatan.

Kata Kunci: K3, Keselamatan, Kesehatan, Kerja

ABSTRACT

OCCUPATIONAL HEALTH AND SAFETY (K3) ANALYSIS ON THE PERTAMINA GEOTHERMAL ENERGY PROJECT PENDINAIAN VILLAGE, SEMENDO DARAT LAUT DISTRICT SOUTH SUMATRA PROVINCE

M. Ridho Erlandi
Ir. Yuliantini Eka Putri,S.T,M.T
Ir. Marinda Gusti Akhiria,S.T,M.T

Performance is the overall level of success of an individual in carrying out tasks within a specific period compared to various possibilities, such as predetermined and mutually agreed upon work standards, targets, or performance targets. This can be achieved if the company consistently prioritizes occupational health and safety (OHS) factors, as this will improve employee performance. A common problem in companies today is the lack of attention to human factors. Research and analysis of occupational health and safety (OHS) at the PT Pertamina Geothermal Energy (PGE) project in Semendo Darat Laut District revealed several conclusions. While OHS implementation has been implemented, several shortcomings have impacted its effectiveness. The primary risk factors include inadequate lighting in the work area and inadequate supervision of safety procedures.

Keywords: OHS, Safety, Health, Work